


Wednesday, November 13, 2002



Clark New Homes
55 Wray Street
Mt Evelyn VIC 3796

Dear Stacey

Recently I spoke to William, who I believe is a contracted working on our home. He mentioned that a delivery driver rolled a load of timber of the side of our block, the load happened to roll over our water tap and meter. The meter is currently dripping slowly and the tap has been bent over. As you can imagine a slow leak is not the best with our present water restrictions. I am not sure who the driver was, you would need to ask William.

Thank you for your help and assistance.

Regards,

Shane Morrison

P.S Both Kim & myself are really pleased with the quality of the work being done, its good to see the home taking shape.