

19TH August 199910
HARMONIOUS BLEND BUILDING CORP.

RE: LOT 10 WOODI YALOCK RD COCKATOO - Adam Mizzi

We visited the site 17.8.99 and are very pleased with the work done by the carpenter - he is doing a great job. There are however still a few things that need to be fixed.

1. Bath needs to be replaced because of chipped corner.
2. Vanity basin needs to be Almond Ivory not white.
3. Balustrade (2nd + 3rd bedroom end) needs to be straightened, both rails need to be in line with the others looking across from the top of the stairs.
4. Kitchen bench (internal left corner) has not been joined properly - causing a lip as well as a gap near the floor.
5. It has also been noticed that the bottom step of the external stairs has a large knot right in the middle on the underside - this is making the step weak.

It would be appreciated if these items could be rectified. Regards
Melissa Rogers *per* Adam Mizzi